

R261 SUPER POWER AIR FRESHENER CRANBERRY

1. Identification of the substance/mixture and of the company/undertaking

1.1 Product identifier

Trade name: SUPER POWER AIR FRESHENER CRANBERRY

Article number: R261

1.2 Relevant identified uses of the substance or mixture and uses advised against

1.3 Details of the supplier of the safety data sheet

Manufacturer/Supplier: Tygris Industrial

Unit 31

Kyle Road Industrial Estate

Irvine Ayshire KA12 8LE

Tel +44 (0) 1294 311 066 Fax +44 (0) 1294 277 115

Email technical@tygrisindustrial.com

Further information obtainable from:

Technical Department

1.4 Emergency telephone

number:

Tel +44 (0) 1294 311 066



R261 SUPER POWER AIR FRESHENER CRANBERRY

2. Hazards identification

2.1. Classification of the substance or mixture

Classification (EC Physical and Cl

Physical and Chemical Hazards Flam. Aerosol 1: H222;

Human health Not classified.

Environment -: H229

Most important adverse

effects

Extremely flammable aerosol. Pressurised container: May burst if heated.

The Full Text for all R-Phrases and Hazard Statements are Displayed in Section 16.

2.2. Label elements

Label In Accordance With (EC) No. 1272/2008



Signal Word Danger

Hazard Statements H222: Extremely flammable aerosol.

H229: Pressurised container: May burst if heated

Precautionary Statements P102: Keep out of reach of children.

P210: Keep away from heat, hot surfaces, sparks, open flames and other ignition

sources. No smoking.

P211: Do not spray on an open flame or other ignition source.

P251: Do not pierce or burn, even after use.

P410+412: Protect from sunlight. Do not expose to temperatures exceeding 50 °C.

2.3. Other hazards In use, may form flammable / explosive vapour-air mixture.

PBT: This product is not identified as a PBT/vPvB substance.



R261 SUPER POWER AIR FRESHENER CRANBERRY

3. Composition/information on ingredients

3.2. Mixtures

BUTANE	10-30%		
Index No.	REACH Registration No.		
CAS-No.: 106-97-8	EINECS: 203-448-7		
Classification (EC 1272/2008) Flam. Gas 1 - H220	Classification (67/548/EEC)		
ISOBUTANE	1-10%		
Index No.	REACH Registration No.		
CAS-No.: 75-28-5	EINECS: 200-857-2		
Classification (EC 1272/2008) Flam. Gas 1 - H220	Classification (67/548/EEC)		
ETHANOL	30-50%		
Index No.	REACH Registration No.		
CAS-No.: 64-17-5	EINECS: 200-578-6		
Classification (EC 1272/2008) Flam. Liq. 2: H225	Classification (67/548/EEC)		
PROPANE	30-50%		
Index No.	REACH Registration No.		
CAS-No.: 74-98-6	EINECS: 200-827-9		
Classification (EC 1272/2008) Flam. Gas 1 - H220	Classification (67/548/EEC)		
METHANOL	1-10%		
Index No.	REACH Registration No.		
CAS-No.: 67-56-1	EINECS: 200-659-6		
Classification (EC 1272/2008) Flam. Liq. 2: H225; Acute Tox. 3: H331; Acute Tox. 3: H311; Acute Tox. 3: H301; STOT SE 1: H370	Classification (67/548/EEC) -		

The Full Text for all R-Phrases and Hazard Statements are Displayed in Section 16



R261 SUPER POWER AIR FRESHENER CRANBERRY

4. First aid measures

4.1. Description of first aid measures

Inhalation Remove casualty from exposure ensuring one's own safety whilst doing so. Move

the exposed person to fresh air. Consult a doctor.

Ingestion Do not induce vomiting. Consult a doctor.

Skin contact Wash immediately with plenty of soap and water.

Eye contact Bathe the eye with running water for 15 minutes. Consult a doctor.

4.2. Most important symptoms and effects, both acute and delayed

Inhalation There may be a feeling of tightness in the chest with shortness of breath.

Ingestion There may be irritation of the throat.

Skin contact There may be mild irritation at the site of contact.

Eye contact There may be irritation and redness.

4.3. Indication of any immediate medical attention and special treatment needed

5. Firefighting measures

5.1 Extinguishing Media

Extinguishing media Alcohol resistant foam. Water spray. Carbon dioxide. Dry chemical powder.

5.2. Special hazards arising from the substance or mixture

Exposure hazards Highly flammable. Forms explosive air-vapour mixture. Vapour may travel

considerable distance to source of ignition and flash back.

5.3. Advice for firefighters

Advice for fire-fighters Wear self-contained breathing apparatus. Wear protective clothing to prevent

contact with skin and eyes.

6. Accidental release measures

6.1. Personal precautions, protective equipment and emergency procedures

Refer to section 8 of SDS for personal protection details. Notify the police and fire brigade immediately. Eliminate all sources of ignition.

6.2. Environmental precautions

Do not discharge into drains or rivers.

6.3. Methods and material for containment and cleaning up

Clean-up procedures Do not use equipment in clean-up procedure which may produce sparks. Absorb

into dry earth or sand. Clean-up should be dealt with only by qualified personnel

familiar with the specific substance.

6.4. Reference to other sections

Refer to section 8 of SDS.

Compilation Date: 22/07/2015 Page 4 of 8



R261 SUPER POWER AIR FRESHENER CRANBERRY

7. Handling and storage

7.1 Precautions for safe handling

Smoking is forbidden. Use non-sparking tools. Ensure there is sufficient ventilation of the area. Do not handle in a confined space. Avoid the formation or spread of mists in the air.

7.2. Conditions for safe storage, including any incompatibilities

Storage conditions Store in a cool, well ventilated area. Keep container tightly closed. Keep away from

sources of ignition. Prevent the build up of electrostatic charge in the immediate

area. Ensure lighting and electrical equipment are not a source of ignition.

Suitable packaging Must only be kept in original packaging.

7.3. Specific end use(s)

8. Exposure controls/personal protection

8.1. Control parameters

Name	STD	TWA - 8 Hrs	STEL - 15 Min	
PROPANE	WEL	1800 mg/m3	7200 mg/m3	
ETHANOL	WEL	1920 mg/m3		
BUTANE	WEL	1450 mg/m3	1810 mg/m3	
ISOBUTANE	WEL	2400 mg/m3	9600 mg/m3	
METHANOL	WEL	266 mg/m3	333 mg/m3	

WEL = Workplace Exposure Limits

8.2. Exposure controls

Protective equipment





equipment are not a source of ignition.

Respiratory equipment Respiratory protection not required.

Hand protection Protective gloves. Chemically resistant gloves.

Eye protection Safety glasses. Ensure eye bath is to hand.

Other Protection Protective clothing.



R261 SUPER POWER AIR FRESHENER CRANBERRY

9. Physical and chemical properties

9.1. Information on basic physical and chemical properties

Appearance Aerosol

Colour Colourless.

Odour Pleasant

Flash point°C -60

9.2. Other information

10. Stability and reactivity

10.1. Reactivity

Stable under recommended transport or storage conditions.

10.2. Chemical stability

Stable under normal conditions. Stable at room temperature.

10.3. Possibility of hazardous reactions

Hazardous reactions will not occur under normal transport or storage conditions.

Decomposition may occur on exposure to conditions or materials listed below.

10.4. Conditions to avoid

Heat. Hot surfaces. Sources of ignition. Flames.

10.5. Incompatible materials

Strong oxidising agents. Strong acids.

10.6. Hazardous decomposition products

No data available.



R261 SUPER POWER AIR FRESHENER CRANBERRY

11. Toxicological information

11.1. Information on toxicological effects

Hazardous ingredients

ETHANOL

IVN	RAT	LD50	1440	mg/kg			
ORL	MUS	LD50	3450	mg/kg			
ORL	RAT	LD50	7060	mg/kg			
METHANOL							
IVN	RAT	LD50	2131	mg/kg			
ORL	MUS	LD50	7300	mg/kg			
ORL	RAT	LD50	5628	mg/kg			

Inhalation There may be a feeling of tightness in the chest with shortness of breath.

Ingestion There may be irritation of the throat.

Skin contact There may be mild irritation at the site of contact.

Eye contact There may be irritation and redness.

12. Ecological information

12.1. Toxicity

12.2. Persistence and degradability

Biodegradable.

12.3. Bioaccumulative potential

No bioaccumulation potential.

12.4. Mobility in soil

Readily absorbed into soil.

12.5. Results of PBT and vPvB assessment

This product is not identified as a PBT/vPvB substance.

12.6. Other adverse effects

Negligible ecotoxicity.

13. Disposal considerations

13.1. Waste treatment methods

Transfer to a suitable container and arrange for collection by specialised disposal company. Dispose of contents and container according to national regulations.



R261 SUPER POWER AIR FRESHENER CRANBERRY

14. Transport information

14.1. UN number

UN Number 1950

14.2. UN proper shipping name

Proper Shipping Name AEROSOLS

14.3. Transport hazard class(es)

ADR/RID/ADN Class 2

14.4. Packing group

14.5. Environmental hazards

Environmentally Hazardous No **Substance/Marine Pollutant**

14.6. Special precautions for user

Tunnel code D

Transport category 2

14.7. Transport in bulk according to Annex II of MARPOL73/78 and the IBC Code

15. Regulatory information

15.1. Safety, health and environmental regulations/legislation specific for the substance or mixture

15.2. Chemical safety assessment

16. Other information

Phrases used in s.2 and s.3 H220: Extremely flammable gas.

H222: Extremely flammable aerosol.

H225: Highly flammable liquid and vapour.

H229: Pressurised container: May burst if heated

H301: Toxic if swallowed.

H311: Toxic in contact with skin.

H331: Toxic if inhaled.

H370: Causes damage to organs <or state all organs affected, if known> <state route of exposure if it is conclusively proven that no other routes of exposure cause the hazard>.

DISCLAIMER

This information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process. Such information is, to the best of the company's knowledge and belief, accurate and reliable as of the date indicated. However, no warranty guarantee or representation is made to its accuracy, reliability or completeness. It is the user's responsibility to satisfy himself as to the suitability of such information for his own particular use.